



Merlyn Products, Inc.  
West 7500 Park Drive  
Spokane, WA 99224-5726  
509-838-7500

## Mandatory Inspection: February 12, 2008

# SAFETY OF FLIGHT INSPECTION

**DISCUSSION:** Two Aircraft equipped with STC SA53NW engine mounts have reported loose lower engine mount attach bolts. (SN: 020004070 and SN: 020307077).

**ACTION:** 1. BEFORE FURTHER FLIGHT, CHECK THE TORQUE ON THE LOWER ENGINE MOUNT BOLTS. Torque should be 28 – 32 ft lbs.

2. REPORT BY PHONE, FAX OR E-MAIL TO:

MERLYN PRODUCTS, INC.

Toll Free: 800-828-7500

Main: 509-838-7500

FAX: 509-838-7501

Cell: 509-995-4616

Email: [suzanne@merlynproducts.com](mailto:suzanne@merlynproducts.com)

Contact: Suzanne Evans

3. Your response is considered URGENT

Please provide the following information:

Aircraft Serial Number: \_\_\_\_\_ (required)

Aircraft Registration #: \_\_\_\_\_ (required)

Date Mount Installed: \_\_\_\_\_ (required)

Engine Mount SN: \* \_\_\_\_\_

Aircraft Total time: \_\_\_\_\_ (required)

Engine mount time in service: \_\_\_\_\_

Report: (facing forward, as seated in aircraft)

Left bolt: (torque value) \_\_\_\_\_

Right bolt: (torque value) \_\_\_\_\_

\*Mounts from Machen, Inc or Merlyn Products, Inc. between 1975 and 2007.